



High Tech Computer Corporation Technical Service Advisory				S/A Number: DOC-00010481					
Issue Date: 2005/06/10	Revision: A01	Affected P/N 99HAK0XX-02 99HAK0XX-03	Description: Repair notice for Magician M/B and LCM difference	Effective Date: 2005/06/10					
Subject: Magician Repair Notice for Toppoly M/B									
Areas Affected: () S/W Release () FRU Inventory () Parts Inventory (X) Documentation () Others		Location: (X) HTC TWN, UK, USA (X) WW ASP		ASP site: Implement Date: Repair Leader (Sign here):					
Notice: Magician repair notice for Toppoly LCM & M/B implement									
Description: 1. HTC implements 2 nd source LCM of supplier Toppoly for Magician , the collocation table of main-board ,LCM , ROM code & camera as follow.									
FRU MB P/N	PCB P/N	GSM	Version	LCM P/N	Vendor	Bezel	Camera	Version	Code
99HAK0XX-02	51H00260-00	900	B06	60H00032-00	Samsung	New/Old	54H00108-00M 54H00093-00	9650 9640	9650: CE 1.06 9640: CE 1.01&1.03
99HAK0XX-03	51H00260-02	900	C02	60H00037-00M	Toppoly	New	54H00108-00M 54H00093-00	9650 9640	CE 1.11
99HAK0XX-02	51H00260-04	900	C01	60H00032-00	Samsung	New/Old	54H00108-00M 54H00093-00	9650 9640	CE 1.11
99HAK0XX-02	51H00260-05	850	C01	60H00032-00	Samsung	New/Old	54H00108-00M	9650	CE 1.11
Magician FUR P/N Main Board definition									
99HAK0XX-02		FRU M/B Samsung							
99HAK0XX-03		FRU M/B Toppoly							
2. New Bezel phase in for Toppoly : New Bezel could be used to Toppoly & Samsung LCM , Old Bezel only to suit Samsung LCM. Please refer to attach photo to identify :									
New					Old				
									
Sponge 1.8mm					Sponge 2.3mm				
NS + NT					Empty (without Logo)				

3. Toppoly LCM product can be identified from Regulation Label by "T01"



**Toppoly
LCM unit**

4. Please ensure your repair technician gets this notice and implements it on repair.

[Follow Up Action from HTC]

Please feedback HTC once you catch this notice.

Originator: HB_Chen	Approved By: Jonathan_Chang	HTC Contact: Tel: 886-3-3753252 # 5988 E-Mail : HB_Chen@HTC.com.tw
-------------------------------	---------------------------------------	---

- *Please have an internal short meeting to make sure all engineers and related personnel understand and catch the notice. Then reply the email back to HTC confirm receiving within 2 days.
HTC FAX NO: +886-3-3755064*