


High Tech Computer Corporation Technical Service Advisory			S/A Number: DOC000-10704	
Issue Date: 2005/6/29	Revision: A01	Affected P/N Magician (MDA compact)	Description: Microphone boot new material cut in notice	Effective Date: 2005/7/1
Subject: Magician Repair Notice				
Areas Affected: () S/W Release () FRU Inventory (X) Parts Inventory () Documentation () Others		Location: (X) T-Mobile ASP	ASP site: Implement Date: Repair Leader (Sign here):	
Notice: Magician (MDA Compact) Microphone boot new material cut in notice				
Description: 1. Cut in the MIC boot (P/N : 76H00777-00M) to improve sound quality. 2. Pls segregate the old (black color) MIC boot . 3. Pls report the on hand Q'ty of the MIC boot to HTC , HTC will provide disposal instruction separately. Will change the color to identify (Part Number will remain the same)				
<p style="text-align: center;">old part--> black New part --> gray</p> 				
New MIC boot part to suit all returned RMA units.				
[Follow Up Action from HTC] Please cut in, once you received the new material				
Originator: HB_Chen	Approved By: Jonathan_Chang	HTC Contact: Tel: 886-3-3753252 # 5988 E-Mail : HB_Chen@HTC.com.tw		

- *Please have an internal short meeting to make sure all engineer and related personnel understand and catch the notice. Then reply the email back to HTC confirm receiving with in 2 days.
HTC FAX NO:+886-3-3755064*